

Inspection Photos
Operator: BP America
Location/API #: 067-07425
Date: 7-10-2019



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern project area from the southwestern edge facing eastward. Vegetation is largely weeds such as cheatgrass (*Bromus tectorum*) and kochia (*Kochia scoparia*).



Photo 3. View of the southern project area from the southeastern corner facing westward.




Photo 4. View of the beginning of vegetation “Transect 1” facing eastward.



Photo 5. View of jointed goatgrass (*Acroptilon repens*) growing within the southwestern portion of the project area.