

Inspection Photos
Operator: BP America
Location/API #: 067-07136
Date: 7-11-2019



Photo 1. View of eastern project area from the northeastern corner facing southward.



Photo 2. View of cement debris, approximately 6 feet long and 4 feet wide within the northeastern project area.



Photo 3. View of barbed wire debris within the northeastern project area.



Photo 4. View of bagged soil amendments and unknown materials within the southern project area.