

Inspection Photos

07/19/2019

Operator: NIGHTHAWK PRODUCTION LLC -
10399

Location ID: 413944
Lincoln County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos

Operator Name: NIGHTHAWK PRODUCTION LLC - 10399

Location ID: 413944



Photo 1: Photo taken from the east end of the location, facing southwest. Photo shows location. Photo also shows drop-gate for location is in disrepair.



Photo 2: Photo taken from the east end of the location, facing west. Photo shows vegetation over the reclamation area. Large areas of the location remains bare and exposed soil. Grazing pressure evident and may be hindering reclamation.

Inspection Photos

Operator Name: NIGHTHAWK PRODUCTION LLC - 10399

Location ID: 413944



Photo 3: Photo taken from location. Photo shows vegetation over the reclamation area. Large areas of the location remains bare and exposed soil.



Photo 4: Photo of vegetation over the reference area.