

Inspection Photos

API: 071-09543

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 7/22/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09543 | Date: 7/22/2019

Inspection Photos



Photo 1. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09543 | Date: 7/22/2019

Inspection Photos



Photo 2. Facing northeast at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09543 | Date: 7/22/2019

Inspection Photos



Photo 3. Facing northwest toward the slope. There are numerous noxious weeds along the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09543 | Date: 7/22/2019

Inspection Photos



Photo 4. There are numerous noxious weeds Musk thistle growing throughout the site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09543 | Date: 7/22/2019

Inspection Photos



Photo 5. Facing southwest at the location. There are areas spars of vegetation and there is still cover crop growth throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09543 | Date: 7/22/2019