

Final Reclamation Inspection

July 17, 2019

Operator: SRC ENERGY INC- #10311

Location ID: 305977

Inspection Document #: 697500363

Weld County, CO

NWSE Section 8 T5N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: MOEN J #8-10
Location ID: 305977



Photo 1. Photo taken of the tank battery, facing North. Photo illustrates equipment that remains at the tank battery location after plugging all associated wells. Operator shall comply with the Rule 1004 standards regarding Final Reclamation activities.