

Construction and Stormwater Inspection

July 22, 2019

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 465709

Inspection Document #: 697500372

Larimer County, CO

SENE Section 25 T5N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: JODSTER SOUTH /24-25HZ PAD
Location ID: 465709



Photo 1. Photo taken from the southeastern location, facing North. Ditch and berm BMP has been installed around the entire perimeter of the location in conjunction with other BMPs (i.e., sediment traps).



Photo 2. Photo taken from the eastern location, facing North. Photo illustrates a water truck on location.

Inspection Photos
Location Name: JODSTER SOUTH /24-25HZ PAD
Location ID: 465709



Photo 3. Photo taken from the eastern location, facing West. Photo illustrates a topsoil stockpile.



Photo 4. Photo taken from the northeastern location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: JODSTER SOUTH /24-25HZ PAD
Location ID: 465709



Photo 5. Photo taken from the northeast location, facing West. See comments under Photo 1.



Photo 6. Photo taken from the southwestern location, facing South. Operator started topsoil salvage operations and plans to salvage all topsoil.