

Inspection Photos
Location Name: ANSON 12-19
API#: 05-071-09674
INSP. #: 695101105



Colorado Oil & Gas Conservation Commission
37.24579, -104.72117, 2182.0m, 280°
2019/07/23 07:36:55



Colorado Oil & Gas Conservation Commission
37.24561, -104.72112, 2178.0m, 209°
2019/07/23 07:55:25

PHOTO 1: WELLHEAD

PHOTO 2: WELL SIGN

Inspection Photos
Location Name: ANSON 12-19
API#: 05-071-09674
INSP. #: 695101105



**PHOTO 3: UNUSED EQUIPMENT STORED ON LOCATION.
REMOVE UNUSED EQUIPMENT. COMPLY WITH RULE 603. CA
DATE 8/24/19**

**PHOTO 4: WEED OVERGROWTH AROUND SURFACE
EQUIPMENT. COMPLY WITH RULE 603. CA DATE 8/3/19.**

Inspection Photos
Location Name: ANSON 12-19
API#: 05-071-09674
INSP. #: 695101105



PHOTO 5: Vacuum pump observed on well without COGCC approval. Provide COGCC with documentation showing approval of use of vacuum pump. CA DATE 8/8/19.