

Inspection Photos  
Location Name: BIG TIMER 32-19 TR  
API#: 05-071-08761  
INSP. #: 695101110



PHOTO 1: WELLHEAD



PHOTO 2: WELL SIGN





## Inspection Photos

Location Name: BIG TIMER 32-19 TR

API#: 05-071-08761

INSP. #: 695101110



**PHOTO 3: UNUSED EQUIPMENT STORED ON LOCATION.  
REMOVE UNUSED EQUIPMENT COMPLY WITH RULE 603 CA  
DATE 8/23/19.**



**PHOTO 4: GUY LINE ANCHOR MARKER DOWN. REINSTALL GUY  
LINE ANCHOR MARKER COMPLY WITH RULE 1003. CA DATE  
8-23-19.**



## Inspection Photos

Location Name: BIG TIMER 32-19 TR

API#: 05-071-08761

INSP. #: 695101110



**PHOTO 5: AREA OF IMPACTED SOIL APPEARS TO BE OIL FROM COMPRESSOR. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 8-23-19**



**PHOTO 6: Noxious weeds including (species) observed in (geographic area of by equipment) part of location. Invasive non-native weeds located (area of location). Comply with Rule 1003.f. CA DATE 7-29-19**