

# Inspection Photos

07/23/2019

Operator: GRAND MESA OPERATING CO #  
35080

Location ID: 456610  
Lincoln County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

**Inspection Photos**  
**Operator Name: GRAND MESA OPERATING CO # 35080**  
**Location ID: 456610**



**Photo 1:** Photos 1-4 taken from the south end of the location, facing west, northwest, northeast to east. Photos show overview of the location. Photos show soils have been replaced and location recontoured/regraded. However, unable to find evidence that location has had revegetation/reseeding activities conducted.



**Photo 2:** See comments under photo 1.

## Inspection Photos

Operator Name: GRAND MESA OPERATING CO # 35080

Location ID: 456610



**Photo 3:** See comments under photo 1.



**Photo 4:** See comments under photo 1.

## Inspection Photos

Operator Name: GRAND MESA OPERATING CO # 35080

Location ID: 456610



**Photo 5:** Photo taken from the southwest corner of the location, facing northwest. Photo show soils have been replaced and location recontoured/regraded. However, unable to find evidence that location has had revegetation/reseeding activities conducted.



**Photo 6:** Photo taken from the northwest end of the location, facing east. Photo show soils have been replaced and location recontoured/regraded. However, unable to find evidence that location has had revegetation/reseeding activities conducted.



## Inspection Photos

Operator Name: GRAND MESA OPERATING CO # 35080

Location ID: 456610



**Photo 7:** Photo taken from the location, facing north. Photo shows vehicle/equipment travel has re-disturbed the interim areas



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources