

Inspection Photos
Location Name: Renfro PAD
Location ID: 432771



Colorado Oil and Gas Conservation Commission
40.51772, -104.72054, 1456.1m, 249°
Jul 24, 2019 13:28:21

Photo 1: Tank Battery Signs



Colorado Oil and Gas Conservation Commission
40.51754, -104.72037, 1452.3m, 289°
Jul 24, 2019 13:19:36

Photo 2: Location



Inspection Photos
Location Name: Renfroe PAD
Location ID: 432771



Photo 3: REPLACE NFPA PLACARD



Photo 4: Unused riser



Inspection Photos
Location Name: Renfroe PAD
Location ID: 432771



Photo 5: Trash found here



Photo 6: Trash next to separator



Inspection Photos
Location Name: Renfro PAD
Location ID: 432771



Photo 7: Trash found here



Photo 8: Trash near west separator



Inspection Photos
Location Name: Renfroe PAD
Location ID: 432771



Photo 9: Compressor




Photo 10: Soil starting to create hole.

