

Inspection Photos
Location Name: Moonshine 36-11-65
Location ID: 417959



Photo 1 – Sign



Photo 2 – Pumping Unit

Inspection Photos
Location Name: Moonshine 36-11-65
Location ID: 417959



Photo 3 – Weeds at Pumping Unit




Photo 4 – Weeds at Pumping Unit



Inspection Photos
Location Name: Moonshine 36-11-65
Location ID: 417959



Photo 5 – Weeds at Flare and ECD



Photo 6 – Weeds at Tank Battery

Inspection Photos
Location Name: Moonshine 36-11-65
Location ID: 417959



Photo 7 – Stained Soil at Wellhead



Photo 8 – Wellhead appears to be leaking,

Inspection Photos
Location Name: Moonshine 36-11-65
Location ID: 417959




Photo 9 – Stained Soil and trash inside Engine House



Photo 10 – Trash inside the Engine House and unused day barrel