

Inspection Photos

Location Name: ANSON 12-19 SOUND STUDY

API#: 05-071-09674

INSP. #: 695101105



Colorado Oil & Gas Conservation Commission
37.24579, -104.72117, 2182.0m, 280°
2019/07/23 07:36:55



Colorado Oil & Gas Conservation Commission
37.24561, -104.72112, 2178.0m, 209°
2019/07/23 07:55:25

PHOTO 1: WELLHEAD

PHOTO 2: WELL SIGN

Inspection Photos

Location Name: ANSON 12-19 SOUND STUDY

API#: 05-071-09674

INSP. #: 695101



PHOTO 3: VIEW OF SPOT OF SOUND STUDY EQUIPMENT IN RELATION TO EQUIPMENT ON LOCATION APPROXIMATELY 70' TO THE NORTH AT THE EDGE OF THE PAD BETWEEN LOCATION SURFACE EQUIPMENT AND COMPLAINTANTS HOME.