

Laramie Energy LLC
API # 05-077-08919
Inspection # 696600378



Photo at entrance of location contains Delta information

Laramie Energy LLC
API # 05-077-08919
Inspection # 696600378



Photo #1 Photo at tank battery on location



Photo #2 Photo at entrance to location.

Laramie Energy LLC
API # 05-077-08919
Inspection # 696600378



Photo #3 Photo of tank battery



Photo #4 photo at wellheads