

Laramie Energy LLC  
API # 05-077-08096  
Inspection # 696600391



Photo #1 Photo of battery sign at entrance to location  
Sign contains Delta information

Photo #2 Photo at entrance to location.

Laramie Energy LLC API  
# 05-077-08096  
Inspection # 696600391



Photo #3 Photo of tank battery



Photo #4 photo at wellheads

Laramie Energy LLC API  
# 05-077-08096  
Inspection # 696600391



Photo #5 stained gravel inside tank containment



Photo #6 stained gravel inside tank containment

Laramie Energy LLC API  
# 05-077-08096  
Inspection # 696600391



Photo #7 stained gravel inside tank containment



Photo #8 stained gravel inside tank containment

Laramie Energy LLC API  
# 05-077-08096  
Inspection # 696600391



Photo #9 Unmarked Deadman on location



Photo #10 Unmarked Deadman on location