

Inspection Photos
Operator: BP America
Location/API #: 067-07087
Date: 7-19-2019



Photo 1. View of the southwestern project area from the southwestern edge facing eastward.



Photo 2. View of Canada thistles remaining within the southern project area.



Photo 3. View of what appears to be treated Canada thistles within the southern project area.