

Inspection Photos
Location Name: Manenti 20-44
API #: 05-123-28105



Photo 1: Wellhead



Photo 2: Stained soil

Inspection Photos
Location Name: Manenti 20-44
API #: 05-123-28105



Colorado Oil and Gas Conservation Commission
40.55499, -104.79508, 1485.0m, 241°
Jul 25, 2019 14:03:30

Photo 3: Stained soil