

Inspection Photos
Operator: Alan Karchmer
Location/API #: 067-05234
Date: 7-24-2019



Photo 1. View of the project area from the western edge facing center.



Photo 2. View of weeds around tanks needing to be managed.