


**Inspection Photos**  
**Location Name: HENDERSON-67N57W /10SESE**  
**Location #: 331730**



**Photo #1**  
**Henderson 1 (05-123-21201) Wellsite**  
**Bradenhead NOT plumbed to surface**  
**Stained soil**



**Photo #2**  
**Henderson 1 Pumpjack**  
**North side**  
**Stained soil**  
**Trash – Old belts**

**Inspection Photos**  
**Location Name: HENDERSON-67N57W /10SESE**  
**Location #: 331730**



**Photo #3**  
**Henderson 1 Pumpjack - South side**  
**Stained soil**  
**Unused Equipment – plastic pipe**  
**Incomplete pumpjack safety guard**



**Photo #4**  
**Henderson 1 Engine shed**  
**Stained soil - Outside**

**Inspection Photos**  
**Location Name: HENDERSON-67N57W /10SESE**  
**Location #: 331730**



**Photo #5**  
**Henderson 1 Engine shed**  
*West side*  
**Stained soil**



**Photo #6**  
**Henderson 1 Engine shed**  
**Stained soil - Inside**

**Inspection Photos**  
**Location Name: HENDERSON-67N57W /10SESE**  
**Location #: 331730**



**Photo #7**  
**Henderson 1 Engine shed**  
**Stained soil - Inside**



**Photo #8**  
**Henderson 1 Pumpjack**  
**Unused Equipment – North side**  
**Trash**

**Inspection Photos**  
**Location Name: HENDERSON-67N57W /10SESE**  
**Location #: 331730**



**Photo #9**  
**Henderson 1 Pumpjack**  
**Unused Equipment – North side**  
**Trash**



**Photo #10**  
**Henderson 1 Pumpjack**  
**Chemical pump tank**  
**NO legible contents / hazard label posted**

**Inspection Photos**  
**Location Name: HENDERSON-67N57W /10SESE**  
**Location #: 331730**



**Photo #11**

**Henderson 1 Crude oil tanks**  
**Contents / Hazard labels posted**  
**Capacity NOT posted**  
*prior insp.*



Colorado Oil & Gas Conservation Commission  
40.58335, -103.73577, 1409.0m, 321°  
07/24/2019 03:39:07 PM

**Photo #12**

**Henderson 1 Crude oil tanks**  
**Contents / Hazard labels posted**  
**Capacity remains NOT posted**

**Inspection Photos**  
**Location Name: HENDERSON-67N57W /10SESE**  
**Location #: 331730**



**Photo #13**  
**Henderson 1 Crude oil tanks**  
**Stained soil behind tanks**  
*prior insp.*



**Photo #14**  
**Henderson 1 Crude oil tanks**  
**Stained soil behind tanks remains**

**Inspection Photos**  
**Location Name: HENDERSON-67N57W /10SESE**  
**Location #: 331730**



**Photo #15**

**Henderson 1 West treater**

**Leak: H2O dripping from bottom access plate**



**Photo #16**

**Henderson 1 West treater shed**

**Stained soil**

**Inspection Photos**  
**Location Name: HENDERSON-67N57W /10SESE**  
**Location #: 331730**



**Photo #17**  
**Henderson 1 West treater shed**  
**Trash**



**Photo #18**  
**Henderson 1 East treater shed**  
**Trash**

Inspection Photos  
Location Name: HENDERSON-67N57W /10SESE  
Location #: 331730



Photo #19

Henderson 1 Battery sign  
**Emergency number not legible**  
*prior insp.*



Photo #20

Henderson 1 Battery sign  
**Emergency number NOT valid**  
**Sign barely legible**

**Inspection Photos**  
**Location Name:** HENDERSON-67N57W /10SESE  
**Location #:** 331730



**Photo #21**

**Henderson 1 West treater**

**Bird protection device NOT on stack**



**Photo #22**

**Henderson 1 West treater**

**Bird protection device NOT on stack**

**Inspection Photos**  
**Location Name: HENDERSON-67N57W /10SESE**  
**Location #: 331730**



**Photo #23**  
**Henderson 1 East treater**  
**Unused Equipment**



**Photo #24**  
**Henderson 1 Battery**  
**Trash barrel – Trash NOT contained**

## Inspection Photos

Location Name: HENDERSON-67N57W /10SESE

Location #: 331730



**Photo #25**

**Henderson 1 Pit**

**Stained soil**

**Weeds**

**No netting**

