

Inspection Photos
Location Name: William D Lansdown 1
Location ID: 317613



COLORADO OIL AND GAS CONSERVATION COMMISSION
40.1193, -104.78751, 4861.8ft, 328°
07/25/2019 12:35:06



COLORADO OIL AND GAS CONSERVATION COMMISSION
40.11936, -104.78754, 4869.6ft, 134°
07/25/2019 12:35:31

Pic 1 sign fixed

Pic 2 electric box on ground

Inspection Photos
Location Name: William D Lansdown 1
Location ID: 317613



Pic 3 casing along fence



Pic 4

Inspection Photos
Location Name: William D Lansdown 1
Location ID: 317613



Pic 5



Pic 6 stained soil

Inspection Photos
Location Name: William D Lansdown 1
Location ID: 317613



COLORADO OIL AND GAS CONSERVATION COMMISSION

Pic 7 uncapped lines



COLORADO OIL AND GAS CONSERVATION COMMISSION

Pic 8

Inspection Photos
Location Name: William D Lansdown 1
Location ID: 317613



Pic 9 uncapped risers/possible leak



Pic 10