

Laramie Energy LLC
API # 05-077-09177
Inspection # 696600399



Battery sign at entrance.

Laramie Energy LLC
API # 05-077-09177
Inspection # 696600399



Photo #1 Photo at entrance to location. Tank battery and Separators



Photo #2 Photo at entrance to location looking south toward wellheads

Laramie Energy LLC
API # 05-077-09177
Inspection # 696600399



Photo #3 Photo of tank battery

Photo #4 photo at wellheads

Laramie Energy LLC
API # 05-077-09177
Inspection # 696600399



Photo #5 Stained soil inside tank containment

Photo #6 Stained soil inside tank containment

Laramie Energy LLC
API # 05-077-09177
Inspection # 696600399



Photo #7 Stained soil inside tank containment

Photo #8 Stained soil inside tank containment and photo of tank staining

Laramie Energy LLC
API # 05-077-09177
Inspection # 696600399



Photo #9 Photo of tank staining



Photo # 10 Photo of tank staining

Laramie Energy LLC
API # 05-077-09177
Inspection # 696600399



Photo # 11 Check Dams on location access road, need maintenance

Photo # 12 Check Dams on location access road, need maintenance

Laramie Energy LLC
API # 05-077-09177
Inspection # 696600399



**Photo # 13 . Photo of upstream side of culvert.
Culvert on upstream and downstream side, in need of
maintenance on access road**

**Photo # 14 Photo of upstream side of culvert.
Culvert on upstream and downstream side, in need of
maintenance on access road**

Laramie Energy LLC
API # 05-077-09177
Inspection # 696600399



**Photo # 15 Photo of down stream side of Culvert.
Culvert on upstream and downstream side, in need of
maintenance on access road**

**Photo # 16 Photo of down stream side of Culvert.
Culvert on upstream and downstream side, in need of
maintenance on access road**