

Inspection Photos

Location Name: BEARDON 24-15 WD

API#: 05-071-07016

INSP. #: 695101131



PHOTO 1: WELLHEAD



PHOTO 2: TANK BATTERY



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: BEARDON 24-15 WD

API#: 05-071-07016

INSP. #: 695101131



PHOTO 3: WELL IS SHUT IN 0 PSI ON INJECTION



**PHOTO 4: 3 PSI ON BACKSIDE BETWEEN TBG AND CSG.
MONITORED FOR 15 MIN. NO CHANGE.**

Inspection Photos

Location Name: BEARDON 24-15 WD

API#: 05-071-07016

INSP. #: 695101131



**PHOTO 5: 0 PSI ON BRADENHEAD. MONITORED FOR FLOW
15 MIN. NO FLOW.**



**PHOTO 6: UNUSED EQUIPMENT NEAR TANK BATTERY.
REMOVE UNUSED EQUIPMENT. COMPLY WITH RULE 603. CA
DATE 8/29/19**