

Inspection Photos
Location Name: POLLY 29-23 WD-R
API#: 05-071-09728
INSP. #: 695101132



Colorado Oil & Gas Conservation Commission
37.2274, -104.69855, 2101.0m, 319°
2019/07/29 10:44:44

PHOTO 1: TANK BATTERY



Colorado Oil & Gas Conservation Commission
37.22741, -104.69855, 2101.0m, 341°
2019/07/29 10:44:55

PHOTO 2: WELL SIGN

Inspection Photos

Location Name: POLLY 29-23 WD-R

API#: 05-071-09728

INSP. #: 695101132



PHOTO 3: 0 INJECTION PSI WELL IS SI



**PHOTO 4: 11 PSI ON BACKSIDE BETWEEN TBG & CSG.
MONITORED PSI FOR 15 MIN. NO CHANGE.**

Inspection Photos
Location Name: POLLY 29-23 WD-R
API#: 05-071-09728
INSP. #: 695101132



PHOTO 5: 0 PSI ON BRADENHEAD. MONITORED FOR FLOW FOR 15 MIN. NO FLOW.



PHOTO 6: UNUSED EQUIPMENT ON LOCATION NEAR EAST EDGE ON PIT. REMOVE UNUSED EQUIPMENT COMPLY WITH RULE 603. CA DATE 8/29/19