

Boring Log/Well Completion Diagram: SB-01

PAGE 1 OF 1

DEPTH (FEET)	LITHOLOGY	SAMPLE				OVM/OVA (PPM)	BLOW COUNT (per 0.5 FT)	DEPTH (FT)	WELL CONSTRUCTION DETAIL	COMMENTS
	DESCRIPTION	GRAPHIC LOG	TYPE	NUMBER	RECOVERY %					
0	(0-10') silty SAND - brown, dry, moist @ ~7', loose, very fine to fine-grained, poorly graded, with ~30% silt, N/O, N/S	SM	DP	1	70	2.7	N/A	No well set.	No groundwater encountered.	
				2		2.4				
5			DP	3	75	0.8				
		4		2.0		N/A				
10										
	BoB @ 10'									
15										
20										
25										
30										

DP - Direct Push
N/A - Not Applicable
HC/O - Hydrocarbon Odor
HC/S - Hydrocarbon Staining
HA - Hand Auger
BoB - Bottom of Boring
N/O - No odor
N/S - No staining

START/COMPLETION DATE: 5/31/2019

SAND PACK INTERVAL (FEET): 3-10

PROJECT: FOSTER E UNIT 1 BATTERY

BENTONITE/GROUT INTERVAL (FEET): 0-3

LOGGED BY: S. VOGT

WELL SCREEN INTERVAL (FEET): N/A

DRILLING COMPANY/EQUIPMENT: EAGLE/GEOPROBE

WELL DIAMETER (IN): N/A

BOREHOLE DIAMETER (IN): 3.25

BORING DEPTH (FEET): 10

WELL DEPTH (FEET): N/A

PID INSTRUMENT: MiniRAE 3000

TIME STARTED/COMPLETED: 14:30/14:40

SAMPLE COLLECTION DEPTH (FEET)/TIME: 0-2.5/14:30



EAGLE
ENVIRONMENTAL
CONSULTING, INC.

4101 INCA STREET, DENVER, CO 80211
Ph: 303-433-0479 • F: 303-325-5449