

Inspection Photos  
Location Name: Hirsch Pad  
Location ID: 434056



**Photo 1: Tank Battery**



**Photo 2: Labeling on produced water tank added**

**Inspection Photos**  
**Location Name: Hirsch Pad**  
**Location ID: 434056**



**Photo 3: Labeling on produced water tank added**



**Photo 4: Labeling added to crude oil tank**

Inspection Photos  
Location Name: Hirsch Pad  
Location ID: 434056



Photo 5: Labeling added to crude oil tank



Photo 6: Risers removed

Inspection Photos  
Location Name: Hirsch Pad  
Location ID: 434056



Photo 7: Risers removed



Photo 8: Risers removed

Inspection Photos  
Location Name: Hirsch Pad  
Location ID: 434056



Colorado Oil and Gas Conservation Commission  
40.56304, -104.84159, 1519.8m, 156°  
Jul 30, 2019 13:11:14

**Photo 9: Risers removed**



Colorado Oil and Gas Conservation Commission  
40.56323, -104.84152, 1518.3m, 274°  
Jul 30, 2019 12:16:12

**Photo 10: Trash removed**

**Inspection Photos**  
**Location Name: Hirsch Pad**  
**Location ID: 434056**



**Photo 11: Holes in berm**



**Photo 12: Holes**

Inspection Photos  
Location Name: Hirsch Pad  
Location ID: 434056



**Photo 13: Unused equipment removed; STAINED SOIL PRESENT**




**Photo 14: Stained soil**

Inspection Photos  
Location Name: Hirsch Pad  
Location ID: 434056



**Photo 15: Pump jack sign**



**Photo 16: Stained soil**

Inspection Photos  
Location Name: Hirsch Pad  
Location ID: 434056



**Photo 17: Behind Hirsch 6-24**



**Photo 18: Stained soil behind Hirsch 6-24**

Inspection Photos  
Location Name: Hirsch Pad  
Location ID: 434056



Photo 19: Behind Hirsch 7-24



Photo 20: Stained soil behind Hirsch 7-24