

Inspection Photos
Location Name: Owl Creek 8-64-6 1H
Location ID: 423916




Photo 1 – Pumping Unit, weeds actively growing



Photo 2 – Tank Battery, weeds actively growing

Inspection Photos
Location Name: Owl Creek 8-64-6 1H
Location ID: 423916



Colorado Oil and Gas Conservation Commission
40.69434, -104.59864, 5122.0ft, 26°
07/24/2019 11:37:21



Colorado Oil and Gas Conservation Commission
40.69399, -104.59872, 5143.3ft, 169°
07/24/2019 11:41:17

Photo 3 – Wellhead appears to be leaking. Stained Soil

Photo 4 – Weeds around the ECDs are actively growing