

Inspection Photos
Location Name: Birds of Prey /36-10-61
Location #: 420207



Photo #1

Birds of Prey 36-10-61 (05-123-32505) Wellsite

Shut-In | SI

Weeds



Photo #2

Birds of Prey 36-10-61 Battery

Weeds

Inspection Photos
Location Name: Birds of Prey /36-10-61
Location #: 420207



Photo #3
Birds of Prey 36-10-61 Tank Battery
Weeds – appears mitigated
prior insp.



Photo #4
Birds of Prey 36-10-61 Tank Battery
Weeds – New growth

Inspection Photos
Location Name: Birds of Prey /36-10-61
Location #: 420207



Photo #5
Birds of Prey 36-10-61 Tank Battery
Low berms
prior insp.



Photo #6
Birds of Prey 36-10-61 Tank Battery
Low berms – NOT addressed

Inspection Photos
Location Name: Birds of Prey /36-10-61
Location #: 420207



Photo #7
Birds of Prey 36-10-61 Wellhead
Stained soil
prior insp.



Photo #8
Birds of Prey 36-10-61 Wellhead
Stained soil – NOT addressed

Inspection Photos
Location Name: Birds of Prey /36-10-61
Location #: 420207



Photo #9
Birds of Prey 36-10-61 Treater
Stained soil, equipment



Photo #10
Birds of Prey 36-10-61 Treater
Weeds

Inspection Photos
Location Name: Birds of Prey /36-10-61
Location #: 420207



Photo #11
Birds of Prey 36-10-61 Treater shed
Inside




Photo #12
Birds of Prey 36-10-61 Engine shed
Stained soil

Inspection Photos
Location Name: Birds of Prey /36-10-61
Location #: 420207



Photo #13
Birds of Prey 36-10-61 Battery & Well
Sign