

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/24/2019

Submitted Date:

07/24/2019

Document Number:

695101117**FIELD INSPECTION FORM**

Loc ID 334178 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1801 BROADWAY SUITE 350City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288795	WELL	PR	03/21/2007	GW	071-09149	SUMMERS 21-19 TR	PR

General Comment:

INSPECTION SURVEY DATA SHEET IN ATTACHMENTS SECTION OF THIS INSPECTION HAS BEEN REPLACE WITH CORRECT SURVEY DATA SHEET BY TOM BEARDSLEE 7/25/19 07:50.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type:	#		corrective date
Comment:	Vacuum pump observed on well without COGCC approval.		
Corrective Action:	IMMEDIATELY STOP PRODUCING WELL ON A VACUUM. DO NOT OPERATOR VACUUM EQUIPMENT (COMPRESSOR) WITHOUT COMPLETE COMPLIANCE WITH RULE 331 AND 802.		Date: 07/24/2019

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 288795 Type: WELL API Number: 071-09149 Status: PR Insp. Status: PR

Complaint

Comment: STEVE LABOWSKIE PERFORMED A SOUND STUDY STARTING @ APPROXIMATELY 8:40 A.M. FOR 15 MINUTES. WIND SPEED APP. 0-5 MPH. TEMP 60*
SOUND METER SET @ 60' FROM COMPRESSOR EXHAUST results are 49.7 AVERAGE db (a) calc. to 34.38 db (a) @ 350'.
NOTE OPERATOR HAD JUST RECENTLY ADDED ANOTHER SOUND WALL COMING OFF OF COMPRESSOR HOUSE.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402121303	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4889780
402121438	sound survey data sheet	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4889923
695101118	LOCATION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4889775
695101119	SOUND SURVAY DATA	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4889776