


## Inspection Photos Location #439173



1 location



2 location



## Inspection Photos Location #439173



**3 unmarked tank**



**4 unmarked tank**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos Location #439173



5 Trash in battery



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources