

Inspection Photos

API: 05-073-06369

Operator: NIGHTHAWK PRODUCTION

Inspection Date: 7/25/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-073-06369 | Date: 7/25/2019

Inspection Photos



Photo 1. Facing east along the access road which was requested to remain. There are erosion issues along the road that need to be repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06369 | Date: 7/25/2019

Inspection Photos



Photo 2. Facing east along the access road which was requested to remain. There are erosion issues along the road that need to be repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06369 | Date: 7/25/2019

Inspection Photos



Photo 3. Facing east along the access road closer to the location which was reclaimed. The fence around the road is degraded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06369 | Date: 7/25/2019

Inspection Photos



Photo 4. Wattles are degraded along the reclaimed road which has not revegetated.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06369 | Date: 7/25/2019

Inspection Photos



Photo 5. Facing back to the west at the access road near the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06369 | Date: 7/25/2019

Inspection Photos




Photo 6. Facing east at the location. Perimeter is fenced.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06369 | Date: 7/25/2019

Inspection Photos



Photo 7. Facing east at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06369 | Date: 7/25/2019

Inspection Photos



Photo 8. Facing west at the location. Vegetation is well established at this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06369 | Date: 7/25/2019

Inspection Photos



Photo 9. Facing northeast at the location. Vegetation is well established at this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06369 | Date: 7/25/2019