

# Inspection Photos

API: 05-073-06318

Operator: NIGHTHAWK PRODUCTION

Inspection Date: 7/25/2019



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-073-06318 | Date: 7/25/2019

## Inspection Photos



**Photo 1.** Facing south at the location which is west of active tank battery site. Soils are compacted and vegetation is not establishing.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06318 | Date: 7/25/2019

## Inspection Photos



**Photo 2.** Facing east at the location which is west of active tank battery site. Soils are compacted and vegetation is not establishing.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06318 | Date: 7/25/2019