

Inspection Photos
Location Name: Milton H. Nelson Unit C #1
Location ID: 336262



Photo 1 WH

Photo 2 WH sign is faded and need to be replaced.

Inspection Photos
Location Name: Milton H. Nelson Unit C #1
Location ID: 336262



Photo 3 weeds around electric panel

Photo 4 Noxious not controlled at entrance of location.