

Inspection Photos  
Location Name: Jillson A #3  
Location ID: 333173



Photo 1 WH sign faded and not legible.



Photo 2 Weeds in and around PU and WH.

**Inspection Photos**  
**Location Name: Jillson A #3**  
**Location ID: 333173**



Colorado Oil and Gas Conservation Commission  
40.11864, -105.00119, 1485.5m  
Jul 30, 2019 10:56:44

**Photo 3 Weeds around Electric control panel.**