

Inspection Photos
Location Name: Smuggler /16-10-62
Location #: 418211



Photo #1

Smuggler 16-10-62 (05-123-31853) Wellsite

Shut-In | SI

Weeds

Photo #2

Smuggler 16-10-62 Battery

Weeds

Inspection Photos
Location Name: Smuggler /16-10-62
Location #: 418211



Photo #3
Smuggler 16-10-62 Wellsite
Weeds, stained soil
Bradenhead NOT plumbed to surface
prior insp.



Photo #4
Smuggler 16-10-62 Battery
Weeds & Stained soil appears mitigated
Bradenhead NOW plumbed to surface

Inspection Photos
Location Name: Smuggler /16-10-62
Location #: 418211



Photo #5
Smuggler 16-10-62 Engine shed
Open bucket - Oily waste
prior insp.



Photo #6
Smuggler 16-10-62 Engine shed
Open bucket - Oily waste removed

Inspection Photos
Location Name: Smuggler /16-10-62
Location #: 418211



Photo #7
Smuggler 16-10-62 Engine shed
Stained soil
prior insp.



Photo #8
Smuggler 16-10-62 Engine shed
Stained soil appears mitigated

Inspection Photos
Location Name: Smuggler /16-10-62
Location #: 418211



Photo #9
Smuggler 16-10-62 Treater area
Weeds
prior insp.



Photo #10
Smuggler 16-10-62 Treater area
Weeds appear NOT mitigated

Inspection Photos
Location Name: Smuggler /16-10-62
Location #: 418211



Photo #11
Smuggler 16-10-62 Tanks area
Weeds
prior insp.



Photo #12
Smuggler 16-10-62 Tanks area
Weeds appear NOT mitigated

Inspection Photos
Location Name: Smuggler /16-10-62
Location #: 418211



Photo #13
Smuggler 16-10-62 Engine exhaust
Stained soil
prior insp.



Photo #14
Smuggler 16-10-62 Tanks area
Stained soil appears mitigated

Inspection Photos
Location Name: Smuggler /16-10-62
Location #: 418211



Photo #15
Smuggler 16-10-62 Tank area
Well & Battery sign