

Inspection Photos
Location Name: 697-21A
Location ID: 335476
Inspection Date: July 26, 2019



Photo #1 – Aerial view of 697-21A location (GISOnline Maps).



Photo # - Location sign.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name:697-21A
Location ID: 335476
Inspection Date: July 26,2019



Photo #3 – View of the 3 feet by 4 feet by 6 feet deep excavation located southwest of the separators.



Photo #4 – View of the 1.5 feet by 4 feet by 6 feet deep excavation located southwest of the separators.



Inspection Photos
Location Name:697-21A
Location ID: 335476
Inspection Date: July 26,2019



Photo #5 – View of operator's staff filling in Spill ID 465066 excavation.



Photo #6 – View of LOTO separators.



Inspection Photos
Location Name: 697-21A
Location ID: 335476
Inspection Date: July 26,2019



Photo #7 – View of unused equipment.



Photo #8 – View of trash and unused equipment.



Inspection Photos
Location Name: 697-21A
Location ID: 335476
Inspection Date: July 26,2019



Photo #9 – View of trash and unused equipment.



Photo #10 – View of trash.



Inspection Photos
Location Name: 697-21A
Location ID: 335476
Inspection Date: July 26,2019



Photo #11 – View of trash / debris and unused equipment.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources