

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/24/2019

Submitted Date:

07/25/2019

Document Number:

696600391

**FIELD INSPECTION FORM**

Loc ID 334493 Inspector Name: Wentzel, Dougo On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10433  
Name of Operator: LARAMIE ENERGY LLC  
Address: 1401 SEVENTEENTH STREET #1401  
City: DENVER State: CO Zip: 80202

**Findings:**

- 20 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Clark, Chris		cogccnotifications@laramie-energy.com	<a href="#">All Inspections</a>
Kellerby, Shaun		shaun.kellerby@state.co.us	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221495	WELL	PA	03/03/2009	GW	077-08096	VEGA UNIT 1	PA
278831	WELL	PR	08/08/2007	GW	077-08930	VEGA UNIT 9-41	PR
278832	WELL	PR	08/04/2007	GW	077-08929	VEGA UNIT 9-31	PR
278833	WELL	PR	08/15/2007	GW	077-08928	VEGA UNIT 4-34	PR
279067	WELL	PR	02/13/2006	GW	077-08918	VEGA 9-21	PR
280260	WELL	PR	02/13/2006	GW	077-08951	VEGA 9-32	PR
288132	WELL	PR	06/10/2013	GW	077-09195	VEGA UNIT 9-211	PR
288133	WELL	PR	12/11/2007	GW	077-09194	VEGA UNIT 4-244	PR
288156	WELL	PR	12/11/2007	GW	077-09190	VEGA UNIT 9-321	PR
288157	WELL	PR	08/15/2007	GW	077-09191	VEGA UNIT 4-341	PR
288158	WELL	PR	12/11/2007	GW	077-09192	VEGA UNIT 9-221	PR
288159	WELL	PR	12/11/2007	GW	077-09193	VEGA UNIT 9-224	PR

**General Comment:**

[Routine FIU General Field Inspection](#)

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Battery sign at entrance to location and contains Delta name and emergency contact information		
Corrective Action:	Install sign to comply with Rule 210.b		Date: 08/23/2019
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained gravel inside tank containment		
Corrective Action:	Comply with Rule 603.f .		Date: 08/23/2019
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Bradenhead	# 11		corrective date
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 11		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			

Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	Unmarked Deadman on location		
Corrective Action:	Comply with the 1003a interim reclamation rules. Note: Add additional information as appropriate for the location.	Date:	08/23/2019
Type: Horizontal Heated Separator	# 12		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	400 BBLs			,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	221495	Type:	WELL	API Number:	077-08096	Status:	PA	Insp. Status:	PA
<b>Producing Well</b>									
Comment:	Producing Well								
Corrective Action:					Date:				
Facility ID:	278831	Type:	WELL	API Number:	077-08930	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing Well								
Corrective Action:					Date:				
Facility ID:	278832	Type:	WELL	API Number:	077-08929	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing Well								
Corrective Action:					Date:				
Facility ID:	278833	Type:	WELL	API Number:	077-08928	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing Well								
Corrective Action:					Date:				
Facility ID:	279067	Type:	WELL	API Number:	077-08918	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing Well								
Corrective Action:					Date:				
Facility ID:	280260	Type:	WELL	API Number:	077-08951	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing Well								
Corrective Action:					Date:				
Facility ID:	288132	Type:	WELL	API Number:	077-09195	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing Well								
Corrective Action:					Date:				
Facility ID:	288133	Type:	WELL	API Number:	077-09194	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing Well								
Corrective Action:					Date:				

Facility ID: 288156 Type: WELL API Number: 077-09190 Status: PR Insp. Status: PR

**Producing Well**

Comment:	Producing Well	
Corrective Action:		Date:

Facility ID: 288157 Type: WELL API Number: 077-09191 Status: PR Insp. Status: PR

**Producing Well**

Comment:	Producing Well	
Corrective Action:		Date:

Facility ID: 288158 Type: WELL API Number: 077-09192 Status: PR Insp. Status: PR

**Producing Well**

Comment:	Producing Well	
Corrective Action:		Date:

Facility ID: 288159 Type: WELL API Number: 077-09193 Status: PR Insp. Status: PR

**Producing Well**

Comment:	Producing Well	
Corrective Action:		Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
		Check Dams	Pass			
Ditches	Pass					
		Compaction	Pass			
Gravel	Pass					
		Berms	Pass			
Seeding	Pass					
		Culverts	Pass			
Berms	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>On (Tuesday) (7/23/19) at approximately (1223), I, Inspector Dougo Wentzel, conducted a (Routine FIU General Field Inspection) at (Laramie) (Vega Unit 9-41 ), (API #077-08930) in (Mesa) Colorado. While there, I observed (A Production Operation only.) During this inspection compliance issues were observed: Delta name and emergency contact information are on a Laramie Battery sign at entrance of location. Stained gravel or soil inside tank battery containment Unmarked deadmen on location (Refer to Corrective Action Matrix for comments, corrective actions, and corrective action date). Refer to photograph of observed compliance issue. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC Rules. (if correction actions are identified) This is a summary of inspection report.</p>	wentzeld	07/25/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402121526	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4889978">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4889978</a>
696600393	Inspection 696600391 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4889973">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4889973</a>