

Inspection Photos
Location Name: Wagner 11-65-9-1H
Location ID: 422671



Photo 1 – Pumping Unit



Photo 2 – Tank Battery



Inspection Photos
Location Name: Wagner 11-65-9-1H
Location ID: 422671



Photo 3 – Stained Soil at Wellhead



Photo 4 – Stained Soil at the Arrow Engine

