

Location Name: 431989 – Nugget Unit Wagers (Rem #8703)

Inspection Date: 07/05/2019



Photo # - 1 View north along east side of former tank battery area.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: 431989 – Nugget Unit Wagers (Rem #8703)

Inspection Date: 07/05/2019



Photo # - 2 View northwest from southeast corner of former tank battery area.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: 431989 – Nugget Unit Wagers (Rem #8703)

Inspection Date: 07/05/2019



Photo # - 3 View northwest from southeast corner of oil skim tank excavation and produced water pit

Location Name: 431989 – Nugget Unit Wagers (Rem #8703)

Inspection Date: 07/05/2019



Photo # - 4 View west from southeast corner of oil skim tank excavation and produced water pit



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: 431989 – Nugget Unit Wagers (Rem #8703)
Inspection Date: 07/05/2019



Photo # - 5 View north-northwest from southeast corner of oil skim tank excavation and produced water pit



Location Name: 431989 – Nugget Unit Wagers (Rem #8703)

Inspection Date: 07/05/2019



Photo # - 6 View east from southwest corner of the produced water pit



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: 431989 – Nugget Unit Wagers (Rem #8703)

Inspection Date: 07/05/2019



Photo # - 7 View southeast across the former tank battery from the southwest corner of the produced water pit



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: 431989 – Nugget Unit Wagers (Rem #8703)

Inspection Date: 07/05/2019



Photo # - 7 View southeast across the former tank battery from the southwest corner of the produced water pit



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources