

Calamity Ridge Unit 4401D A23 1N100

API: 05-103-10561

Inspection: 679704921




Photo 1. Location.



Calamity Ridge Unit 4401D A23 1N100

API: 05-103-10561

Inspection: 679704921



Photo 2. Tank label.



Photo 3. Tank liner hole.

Calamity Ridge Unit 4401D A23 1N100

API: 05-103-10561

Inspection: 679704921



Photo 4. Unmarked deadman.



Photo 5. Valve can.

Calamity Ridge Unit 4401D A23 1N100

API: 05-103-10561

Inspection: 679704921



Photo 6. Rods & tubing.



Photo 7. Pump jack missing sign.

Calamity Ridge Unit 4401D A23 1N100

API: 05-103-10561

Inspection: 679704921



Photo 8. Battery sign.



Photo 9. Pump jack weeds.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources