

Inspection Photos

API: 05-017-07298

Operator: WIEPKING-FULLERTON ENERGY

Inspection Date: 7/25/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-017-07298 | Date: 7/25/2019

Inspection Photos



Photo 1. Facing northwest along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07298 | Date: 7/25/2019

Inspection Photos



Photo 2. Facing west at the location. This area is predominately undesirable vegetation. (Kochia sp.)



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07298 | Date: 7/25/2019

Inspection Photos



Photo 3. Facing south at the location. This area is predominately undesirable vegetation. (*Kochia* sp.)



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07298 | Date: 7/25/2019

Inspection Photos



Photo 4. South side of the location facing north. This area is bare of vegetation growth. Approximately 150 ft. x 30 ft..



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07298 | Date: 7/25/2019

Inspection Photos



Photo 5. Facing west at the surrounding undisturbed reference area pasture.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07298 | Date: 7/25/2019