

Inspection Photos

API: 05-055-06077

Operator: OXY USA INC

Inspection Date: 8/1/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06077 | Date: 8/1/2019

Inspection Photos



Photo 1. There are numerous noxious weeds along the main access road traveling to the location past the gate.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06077 | Date: 8/1/2019

Inspection Photos




Photo 2. There are numerous noxious weeds (Common mullein) near all the wells in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06077 | Date: 8/1/2019