

Inspection Photos
Location Name: Cosslett B #2
Location ID: 318470



Photo 1 WH



Photo 2 Stained soil around WH

Inspection Photos
Location Name: Cosslett B #2
Location ID: 318470



Photo 3 WH Sign faded not legible



Photo 4 Stained soil under gear box



Inspection Photos
Location Name: Cosslett B #2
Location ID: 318470



Photo 5 Mechanical issue Gear box bearing appears to be leaking



Photo 6 Stained soil under gear box

Inspection Photos
Location Name: Cosslett B #2
Location ID: 318470




Photo 7 Mechanical issue tubing flow lines appear to be leaking