

## Inspection Photos

Location Name: COTTONTAIL PASS UNIT 31-2 FOLLOWUP

API#: 05-071-06386

INSP. #: 695101155



PHOTO 1: WELLHEAD



PHOTO 2: WELL SIGN/ CURRENT OPERATOR HAS BEEN POSTED HOWEVER 911 IS NOT INCLUDED IN EMERGENCY CONTACT. **COMPLY WITH 210.b. CA DATE 7/11/19.**



## Inspection Photos

Location Name: COTTONTAIL PASS UNIT 31-2 FOLLOWUP

API#: 05-071-06386

INSP. #: 695101155



**PHOTO 3: Vacuum pump observed on well without COGCC approval. Provide COGCC with documentation showing approval of use of vacuum pump. CA DATE 6/26/19**

