

Inspection Photos
Location Name: LILLI UNIT-68N58W /6SESE
Location #: 326799



Photo #1

Lilli Unit 16-6 (05-123-13691) Wellsite
Temporarily Abandoned | TA
No sign or Emergency number posted
prior insp.



Photo #2

Lilli Unit 16-6 Wellsite
Temporarily Abandoned | TA
No sign or Emergency number posted

Inspection Photos
Location Name: LILLI UNIT-68N58W /6SESE
Location #: 326799



Photo #3
Lilli Unit 16-6 Wellsite
Stained soil
Unused Gas supply tank
prior insp.



Photo #4
Lilli Unit 16-6 Wellsite
Stained soil
Unused Gas supply tank

Inspection Photos
Location Name: LILLI UNIT-68N58W /6SESE
Location #: 326799



Photo #5
Lilli Unit 16-6 Battery site
Shut-down
prior insp.



Photo #6
Lilli Unit 16-6 Battery site
Shut-down

Inspection Photos
Location Name: LILLI UNIT-68N58W /6SESE
Location #: 326799



Photo #7

Lilli Unit 16-6 Battery site
Emergency number NOT valid
prior insp.



Photo #8

Lilli Unit 16-6 Battery site
Emergency number NOT valid