

# Inspection Photos

08/02/2019

Operator: WHITING OIL & GAS CORPORATION  
- 96155

Location ID: 435677  
Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

**Inspection Photos**  
**Operator Name: WHITING OIL & GAS CORPORATION - 96155**  
**Location ID: 435677**



**Photo 1:** Photo taken from the east end of the location, facing south. Photos 1-4 provide an overview of the location from south, southwest, northwest to north. Photos show that only the areas of the access road, and immediate areas surrounding the wells appear to have been stabilized. Photo shows large areas that remain unstabilized where stormwater ponding outside of the perimeter ditch is evident.



**Photo 2:** See comments under photo 1.

Inspection Photos  
Operator Name: WHITING OIL & GAS CORPORATION - 96155  
Location ID: 435677



**Photo 3:** See comments under photo 1.



**Photo 4:** See comments under photo 1.



## Inspection Photos

Operator Name: WHITING OIL & GAS CORPORATION - 96155

Location ID: 435677



**Photo 5:** Photo taken from the northwest end of the location, facing east. Photos 5-7 provide an overview of the interim and reclamation areas from east, southeast to south.



**Photo 6:** See comments under photo 5.

## Inspection Photos

Operator Name: WHITING OIL & GAS CORPORATION - 96155

Location ID: 435677



**Photo 7:** See comments under photo 5.



**Photo 8:** Photo taken from the south end of the location, facing west. Photo shows the perimeter stormwater ditch during initial construction activities remaining. Vegetation over interim areas appear to have sufficiently stabilized the soils; Original perimeter stormwater ditch, sediment traps, BMPs etc... no longer appear to be necessary and require reclamation..



## Inspection Photos

Operator Name: WHITING OIL & GAS CORPORATION - 96155

Location ID: 435677



**Photo 9:** Photo taken from the south end of the location, facing east. See comments under photo 8.



**Photo 10:** Photo of sediment trap on the southeast end of the location. See comments under photo 8.

## Inspection Photos

Operator Name: WHITING OIL & GAS CORPORATION - 96155

Location ID: 435677



**Photo 11:** 2017 COGCC COGIS aerial image. Photo shows perimeter stormwater ditch (yellow dotted line) w/ sediment traps, BMPs, etc... that require reclamation

