

# Inspection Photos

08/02/2019

Operator: WHITING OIL & GAS CORPORATION  
- 96155

Location ID: 430127  
Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

## Inspection Photos

Operator Name: WHITING OIL & GAS CORPORATION - 96155

Location ID: 430127



**Photo 1:** Photo taken from the south end of the location, facing west. Photos 1-3 provide an overview of the location from west, northwest, to northeast. Photos show active wells remaining on location. Photos also show that only the areas of the access road, and immediate areas surrounding the wells appear to have been stabilized. Photo shows large areas that remain unstabilized where stormwater ponding outside of the perimeter ditch is evident.

**Photo 2:** See comments under photo 1.

## Inspection Photos

Operator Name: WHITING OIL & GAS CORPORATION - 96155

Location ID: 430127



**Photo 3:** See comments under photo 1.



**Photo 4:** Photo taken from the south end of the location, facing west. Photo shows the perimeter stormwater ditch during initial construction activities remaining. Vegetation over interim areas appear to have sufficiently stabilized the soils; Original perimeter stormwater ditch, sediment traps, BMPs etc... no longer appear to be necessary and require reclamation.

## Inspection Photos

Operator Name: WHITING OIL & GAS CORPORATION - 96155

Location ID: 430127



**Photo 5:** Photo taken from the south east end of the location, facing north. Photo shows the perimeter stormwater ditch and sediment trap during initial construction activities remaining. Vegetation over interim areas appear to have sufficiently stabilized the soils; Original perimeter stormwater ditch, sediment traps, BMPs etc... no longer appear to be necessary and require reclamation.

Photo also shows Canada thistle establishing on sediment trap/ditch. This is a Colorado State listed noxious weed and requires management.




**Photo 6:** Photo shows Canada thistle establishing on sediment trap/ditch. This is a Colorado State listed noxious weed and requires management.

## Inspection Photos

Operator Name: WHITING OIL & GAS CORPORATION - 96155

Location ID: 430127



**Photo 7:** 2017 COGCC COGIS aerial image. Photo shows perimeter stormwater ditch (yellow dotted line) w/ sediment traps, BMPs, etc... that require reclamation. Red circle on the southeast corner of location represents areas where noxious weeds were observed.