

Inspection Photos
Location Name: 596-31A
Location ID: 335875
Inspection Date: July 29, 2019



Photo #1 – Aerial view of location 596-31A (GISOnline Maps).



Photo #2 – Location sign.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: 596-31A
Location ID: 335875
Inspection Date: July 29, 2019



Photo #3 – View of active leak at the process pipe pump control area.



Photo #4 – View of active leak at the process pipe pump control area.



Inspection Photos
Location Name: 596-31A
Location ID: 335875
Inspection Date: July 29, 2019



Photo #5 – Assorted metal equipment and trash stored in secondary containment.



Photo #6 – Metal equipment stored directly on liner.

