

Inspection Photos

API: 05-071-06338

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 8/8/2019



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06338 | Date: 8/8/2019

Inspection Photos



Photo 3. The culvert has filled in with sediment along the main road.

Lat/Long:37.089560/-104.96140



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06338 | Date: 8/8/2019

Inspection Photos



Photo 2. The main road was recently graded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06338 | Date: 8/8/2019