

Inspection Photos

07/01/2019

Operator: FOUNDATION ENERGY
MANAGEMENT LLC # 10112

Location ID: 331849
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC # 10112

Location ID: 331849



Photo 1: Photo taken from the well location, facing northwest. Photo shows location remains predominantly bare and exposed soil. Photo also shows field bindweed establishing on location (white flowers). Unable to find evidence that additional reclamation has been conducted at the well site and access road.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC # 10112

Location ID: 331849



Photo 2: Photo taken from well location. Photo shows Diffuse knapweed remains on location. Photo also shows field bindweed (white flowers)



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC # 10112

Location ID: 331849



Photo 3: Photo taken from the well location, facing west. Photo shows the access road “turn-around”. Photo shows access road/location has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC # 10112

Location ID: 331849



Photo 4: Photo taken from the access road, facing west. Photo shows access road has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC # 10112

Location ID: 331849



Photo 5: Photo taken from the access road. Photo shows Diffuse knapweed and field bindweed (white flowers) along access road.



Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC # 10112

Location ID: 331849



Photo 6: Photo taken from the access road, facing west. Photo shows cattle guard at access road entrance has not been removed, and access road has not been reclaimed. Photo also shows field bindweed along access road (white flowers)



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources