

Inspection Photos

08/08/2019

Operator: FOUNDATION ENERGY
MANAGEMENT LLC - 10112

Location ID: 455471
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 455471



Photo 1: Photo taken from southwest end of the location, facing north. Photo provides an overview of the location.



Photo 2: Photo taken from southwest end of the location, facing northeast. Photo provides an overview of the location.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 455471



Photo 3: Photo taken from south end of the location, facing south. Photo shows Diffuse Knapweed (Plants with white flowers in photo) remains established on the location/access road. Operator has failed to conduct sufficient ongoing noxious weed management on the location.



Photo 4: Photo taken from the southwest end of the location, facing northeast. See comments under photo 3

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 455471



Photo 5: Photo taken from the south end of the location, facing northeast. See comments under photo 3



Photo 6: Photo taken from the southeast end of the location, facing northeast. See comments under photo 3. Photo also shows berm has been repaired per CAs