

**Inspection Photos**  
**Location Name: Waste Management 2I-401**  
**Location ID: 432119**



**Pic 1**



**Pic 2 stained soil by muffler of pumping unit.**

**Inspection Photos**  
**Location Name: Waste Management 2I-401**  
**Location ID: 432119**



**Pic 3 stained soil & no containment for chemicals**



**Pic 4**



**Inspection Photos**  
**Location Name: Waste Management 2I-401**  
**Location ID: 432119**



**Pic 5 unused equipment/trash**



**Pic 6 unused equipment/trash/no containment on chemical tanks/stained soil**

**Inspection Photos**  
**Location Name: Waste Management 2I-401**  
**Location ID: 432119**



**Pic 7 trash/unused equipment/stained soil**



**Pic 8 stained soil/mechanical issues**



**Inspection Photos**  
**Location Name: Waste Management 2I-401**  
**Location ID: 432119**



**Pic 9 stained soil/mechanical issues/spill**



**Pic 10**